

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 32 S., R. 9 W.

36

CHAINS	<p>S.89*48'W., on a true line, bet. secs. 2 and 11. Ascend through scattering timber and dense undergrowth.</p> <p>2.00 Top of ridge, bears N. and S.; descend steep slope through burn.</p> <p>28.50 Rocky bluffs, 30 ft. high, bears N. and S. Enter heavy timber, bears N. and S.</p> <p>30.30 Babes Creek, 15 lks. wide, course NE.; ascend.</p> <p>38.60 Top of spur, slopes S.; descend.</p> <p>40.01 Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked</p> <div style="text-align: center; margin: 10px 0;"> $\frac{1}{4} \frac{S2}{S11}$ 1917 </div> <p>from which</p> <p style="padding-left: 40px;">A tan oak, 8 ins. diam., bears N.16*E., 41 lks. dist., marked $\frac{1}{4}$ S 2 B T.</p> <p style="padding-left: 40px;">A maple, 5 ins. diam., bears S.11*E., 18 lks. dist., marked $\frac{1}{4}$ S 11 B T.</p> <p>40.10 Creek, 1 lk. wide, course S.; ascend E. slope.</p> <p>49.70 Top of spur, slopes SE.; descend.</p> <p>58.00 Creek, 3 lks. wide, course SE.; ascend.</p> <p>75.90 Top of spur, slopes SE.; along S. slope.</p> <p>80.02 The cor. of secs. 2, 3, 10 and 11. Land, mountainous. Soil, shaly clay loam, 3rd rate. Timber, fir, sugar pine and laurel. Undergrowth, tan oak, snowbrush, rhododendron and huckleberry.</p> <hr/> <p>N.0*02'W., on a random line, bet. secs. 2 and 3.</p> <p>40.00 Set temp. $\frac{1}{4}$ sec. cor.</p> <p>70.51 Intersect the N. bdy. of the Tp., 4 lks. W. of the cor. of secs. 2 and 3. Thence South, on a true line, bet. secs. 2 and 3. Descend through heavy timber and dense undergrowth.</p>
--------	--