

## County Surveyor's Record, Douglas County, Oregon

60

Subdivisions of T. 32 S., R. 9 W.

## CHAINS

- Ascend NW. slope, through heavy timber and dense undergrowth.
- 11.85 Ravine, course NW.
- 13.40 Top of spur, slopes NW.
- 15.50 Creek, 3 lks. wide, course NW.; ascend steep slope.
- 28.00 Top of ascent; along flat spur.
- 28.81 Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for  $\frac{1}{4}$  sec. cor., with brass cap marked
- $\frac{1}{4}$   
 S6 | S5  
 1917
- from which
- A fir, 16 ins. diam., bears S.62\*E., 14 lks. dist., marked  $\frac{1}{4}$  S 5 B T.
- A fir, 16 ins. diam., bears N.23\*W., 27 lks. dist., marked  $\frac{1}{4}$  S 6 B T.
- 36.00 Leave spur; along W. slope.
- 59.00 Ravine, course W.
- 68.81 The cor. of secs. 5, 6, 7 and 8.
- Land, mountainous.
- Soil, stony, 4th rate.
- Timber, fir, cedar and laurel
- Undergrowth, rhododendron, snowbrush, chinquapin and tan oak.

## General Description

This township is mountainous over its whole extent, consisting of the Rogue River-Unpqua Divide, which extends through the township. The land suitable for cultivation is limited, consisting of small and scattered areas of bench land. The soil, where not rocky, is of fair quality.

The township as a whole is timbered, but the timber suitable for commercial purposes is scarce and lies generally in small and detached areas. Fir and sugar pine are the only varieties suitable for commercial purposes. There is a sprinkling of ~~decid~~ <sup>Cedar</sup> and considerable laurel or manrona, tan oak, live oak and chinquapin, with alder and maple along the streams.