

Subdivisions of T. 33 S., R. 4 W.

CHAINS

marked T 33 S R 4 W S 4 B T.

A Fir, 6 ins. diam., bears S.63\*W., 34 lks. dist.,

marked T 33 S R 4 W S 5 B T.

A Cedar, 10 ins. diam., bears N.22\*E., 8 lks. dist.,

marked T 33 S R 4 W C C S 4 and 5. B T.

Land, mountainous, broken, rough and high.

Soil, gravelly with rock. 3rd rate.

Heavy timber, Fir, Pine, and Cedar.

Dense underbrush, small Fir, Mountain Laurel, Hazel, Yew,

Chinquapin, and Live Oak, 74.50 chs.

September 11, 1893.

North, 4'W., between secs. 19 and 20.\*\*\*\*\*

80.00

800 ft. above creek at 22.70 chs. set a basaltic stone,

18 x 10 x 6 ins., 12 ins. in the ground, for cor. to

secs. 17, 18, 19 and 20, marked with 3 notches on S.

and 5 notches on E. edges, from which

A Fir, 24 ins. diam., bears N.85\*E., 44 lks. dist.,

marked T 33 S R 4 W S 17 B T.

A Fir, 30 ins. diam., bears S.25\*E., 34 lks. dist.,

marked T 33 S R 4 W S 20 B T.

A Fir, 36 ins. diam., bears S.28\*W., 26 lks. dist.,

marked T 33 S R 4 W S 19 B T.

A Fir, 10 ins. diam., bears N.13\*W., 47 lks. dist.,

marked T 33 S R 4 W S 18 B T.

Land, mountainous, <sup>broken</sup> rough, high.

Soil, gravelly, rocky, 4 th rate.

Heavy timber, Fir, Cedar, and Pine.

Dense undergrowth, small Fir, Hazel, Matherone and

Live Oak, 80.00 chs.

September 17, 1893.

West on a random line between secs. 18 and 19.

Va. 17\*30'E