

Subdivisions of T. 33 S., R. 4 W.

CHAINS	
40.00	Set temp. $\frac{1}{2}$ sec. cor.
78.74	Intersect the West boundary of township 30 lks. North of cor. to secs. 7, 12, 13 and 18.
	Thence I run
	N.89*55'E. on a true line between secs. 7 and 18.
	Va. 19*E
	Ascend mountain on N. rocky slope.
14.70	A Fir, 3 ft. diam., on line, marked with 2 notches on E. and W. sides.
24.30	A Fir, 4 ft. diam., on line, marked with 2 notches on E. and W. sides.
38.74	A Yew, 5 ins. diam., which I marked $\frac{1}{4}$ S. on N. face, for $\frac{1}{4}$ sec. cor., from which
	A W. Fir, 6 ins. diam., bears S.45*E., 24 lks. dist., marked $\frac{1}{4}$ S B T.
	A W. Fir, 8 ins. diam., bears N.79*W., 18 lks. dist., marked $\frac{1}{4}$ S B T.
58.40	A W. Fir, 3 ft. diam., on line marked with 2 notches on E. and W. sides.
64.24	A branch, 4 lks. wide, course N.20*W.
78.74	The cor. to secs. 7, 8, 17 and 18, 800 ft. above Tp. cor. to secs. 7, 12, 13 and 18.
	Land, mountainous, broken, rough, high.
	Soil, gravelly, rocky, 4th rate.
	Heavy timber, Fir, Pine, cedar and Yew.
	Dense underbrush, small Fir, Hazel, Vine Maple and Yew, 78.74 chs.
	September 19, 1893.
	North, 4'W. between secs. 7 and 8.
	Va. 18*50'E
	Descend mountain
18.74	A Fir, 10 ins. diam., on line, marked with 2 notches on N. & S. sides.