

Subdivisions of T. 33 S., R. 5 W.
Same Deputy and Contract.

CHAINS	<p>North 89°35'E on a random line between secs. 13 and 24. Va. 20°E.</p>
40.00	Set tem. $\frac{1}{4}$ sec. cor.
80.20	Intersect E boundary of Tp. 28 lks. S of cor. to secs. 13, 18, 19 and 24, described in the survey of T.33 S., R. 4 W. Thence I run S.89°23'W. on a true line between secs. 13 and 24. Va. 16°E. Ascend gradually.
1.80	A Fir, 24 ins. diam. line tree marked with 2 notches on E and W sides and leave timber.
2.50	Top of mountain +50 and descend mountain on NW slope.
5.50	Enter timber.
14.50	A Fir, 18 ins. diam. line tree marked with 2 notches on E and W sides.
28.00	Branch, 5 lks. wide, course NW.
40.10	A rock, 3 ft. x 3 ft. x 2 ft. above ground in place which I marked $\frac{1}{4}$ on N face for $\frac{1}{4}$ sec. cor. with a (x) cross at exact corner point from which A Fir, 12 ins. diam., bears N.76°E., 79 lks. dist. Marked $\frac{1}{4}$ S B T. A Cedar, 30 ins. diam., bears S.23°30'W., 185 lks. dist, marked $\frac{1}{4}$ S B T.
54.20	Foot of descent, 350 ft. and creek 10 lks. wide, course S. Ascend on SE slope of mountain.
69.00	Leave timber and enter dense Buck-horn, Manzanita, and Chaparral brush, and continue ascending on S slope of mountain.
80.20	The cor. to secs. 13, 14, 23 and 24, 250 ft. above creek. Land, mountainous, broken, rough. Heavy timber, Fir, Cedar and Pine. Dense Buck-horn , Chaparral, and Chinquapin brush. Soil, 3rd rate, gravelly with scattering, large boulders. May 31, 1894.