

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 33 S., R. 5 W.

CHAINS	<p>A Fir, 8 ins. diam., bears S.43°E., 31 lks. dist. marked $\frac{1}{4}$ S B T.</p> <p>41.40 Spur, 50 ft. high bears N.</p> <p>42.75 Ravine, 20 ft. deep and spring branch, 2 lks. wide, course N.</p> <p>47.70 Begin to descend.</p> <p>55.00 Top of bluff, 40 ft. high and a Fir, 20 ins. diam, line tree marked with 2 notches on E and W sides, and descend rapidly into canyon.</p> <p>57.22 Foot of descent and canyon - 250 ft. Creek 10 lks. wide course N.</p> <p>57.32 Foot of sloping bluffs and ascend mt. spur.</p> <p>61.75 Foot of rocky bluff, 60 ft. high and a fir, 24 ins. diam. line tree marked with 2 notches on E and W sides.</p> <p>62.55 Top of mt. spur +200 bears N. Descend rocky slope into canyon.</p> <p>68.20 Foot of descent and canyon -100 and spring branch 1 lk. wide, course N. Ascend rapidly on N slope.</p> <p>69.45 Ascend more gradually on N slope.</p> <p>78.45 Ravine bears N.</p> <p>80.44 The cor. to secs. 11, 12, 13 and 14 .</p> <p>Land, mountainous, broken, very rough and all sloping to the N.</p> <p>Heavy timber of Fir, Pine, Cedar and Yew. Dense undergrowth of small Fir, live Oak, Chinquapin, Yew, Hazel and Vine Maple. Soil 4th rate, gravelly and rocky.</p> <p style="text-align: right;">June 1, 1894.</p>	+250
	<p>North, 1'W between secs 11 and 12.</p> <p style="text-align: right;">Va 21°40'E.</p> <p>Descend mt. NE slope along sloping bluffs.</p> <p>3.40 Foot of bluff and continue descending on NW slope.</p> <p>18.50 Y. Pine 16 ins. diam. line tree marked with 2 notches on N and S sides, and the Va. here is 24$\frac{1}{2}$°E.</p>	