

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T 33 S., R. 5 W.

CHAINS		
12.70	Ascend now on S slope gradually.	
40.25	Begin to ascend on SW slope.	
44.42	<p>The $\frac{1}{2}$ sec. cor. bears N.4 lks. which is a post 3 ins. sq. 12 ins. above ground firmly set, marked $\frac{1}{2}$S on N side from which</p> <p>A Y. Pine, 16 ins. diam., bears N.80*W., 118 lks. dist. with well defined blazes.</p> <p>A Fir, 12 ins. diam., bears S.19$\frac{1}{2}$E., 63 lks. dist. with well defined blazes.</p>	
64.20	Top of ridge, course N.60*W., and along W slope of mt.	
81.95	Head of small stream, 1 lk. wide, course NW.	
84.65	<p>The SE cor. to Tp. 32 S R 5 W which is a post 4 ins. sq. firmly set 2$\frac{1}{2}$ft above ground marked T 32 S R 4 W S 31 on NE., T 33 S R 4 W S 6 on SE., R 5 W S 1 on SW and R 5 W S 36 on NW sides with 6 notches on N S E and W edges from which</p> <p>A Fir, 12 ins. diam., bears N.42*E., 27 lks. dist. with well defined blazes.</p> <p>A Redwood, 36 ins. diam., bears S.58*E., 39 lks. dist with well defined blazes.</p> <p>A Fir, 12 ins. diam., bears S.60*W., 17 lks. dist. with well defined blazes.</p> <p>A Fir, 11 ins. diam., bears N.62*W., 20 lks. dist. with well defined blazes.</p> <p>Land, mountainous, broken, rough.</p> <p>Heavy timber of Fir, Pine Cedar and Laurel.</p> <p>Dense underbrush of small Fir, Hazel, Laurel.</p> <p>Soil 4th rate, gravelly.</p>	+1500
	<p>I now return to the cor. established for the NW cor. of Tp. 33 S R 4 W on Tp. line between secs. 1 and 6 which is a basaltic stone 4 x 12 x 6 ins. above ground</p>	