

County Surveyor's Record, Douglas County, Oregon

12

Subdivisions of T. 33 S., R. 5 W.

CHAINS

marked C C with 6 notches on SE and W edges and is
24.50 chs. W of the standard Tp. cor. to Tps, 32 and
33 S R's. 4 and 5 W, 7th standard,

Parallel South.

I destroy the SW and NE trees referring to the closing
cor. for the NW cor. to Tp. 33 S R 4 W and from which
remains

A Fir, 10 ins. diam., bears S.77*E., 16 lks. dist.

marked T 33 S R 4 W S 6 B T.

Thence I run N on Tp. line projecting the last bdy. of
sec. 1. T 33 S R 5 W.

Descend 150 ft. on N slope of mountain to

5.57 Intersect S bdy. of Tp. 32 S R 5 W which is also N.
bdy. of sec. 1 T 33 S R 5 W.

Marked temp. point for closing cor. from which I run
E on Tp line.

Va 20*E.

Along N. slope of mt.

3.70 Intersect SE cor. of Tp 32 S R ⁵ W, previously described.

I destroyed the marks on the SE and SW trees, also
the marks on the SE and S^w sides of the post, and
notches on the S side.

I now return to the point for closing cor. and set a
stone 10 x 8 x 8 ins. 7 ins. in the ground for closing
cor. to Tp. 33 S R 5 W, marked C C with 6 notches
on SE and W edges from which

A Fir, 10 ins. diam., bears S.45*E., 35 lks. dist.
marked T 32 S R 4 W S 31 B T.

A Fir, 8 ins. diam., bears S.20*W., 29 lks. dist.
marked T 33 S R 5 W S 1 B T.

A Fir, 10 ins. diam., bears N.40*W., 45 lks. dist.
marked C C T 33 S R 5 W B T.