

## County Surveyor's Record, Douglas County, Oregon

14

## Subdivisions of T 33 S., R. 5 W.

CHAINS	<p>Land, mountainous, broken, rough.</p> <p>Heavy timber Fir, Cedar, Pine and Matherone.</p> <p>Dense underbrush Vine Maple, live Oak, Chinquapin and Hazel.</p> <p>Soil, 3rd rate, stony and gravelly.</p> <p style="text-align: right;">June 5, 1893.</p>
	<p>South 89°22'E on a random line between secs. 14 and 23.</p> <p style="text-align: right;">Va 23°E.</p> <p>40.00 Set temp. <math>\frac{1}{4}</math> sec. cor.</p> <p>80.60 Intersect N and S line 11 lks. N of cor. to secs. 13, 14 23 and 24.</p> <p>Thence I run N.89°17'W on a true line between secs. 13 and 23.</p> <p style="text-align: right;">Va 20°E.</p> <p>Along about level on S slope through dense Buck-horn and Chaparral brush, gradually ascending to</p> <p>9.00 Summit of main divide bears N.30°E and S.30°W.</p> <p>Along top of divide gradually ascending to</p> <p>16.50 Descend rapidly on steep W slope, rocky.</p> <p>23.00 Top of bluff 40 ft. high and enter timber.</p> <p>40.30 Set basaltic stone 16 x 10 x 8 ins. 11 ins. in the ground for <math>\frac{1}{4}</math> sec. cor. marked <math>\frac{1}{4}</math> on N side from which A W. Fir, 8 ins. diam., bears N.23°W., 44 lks. dist. marked <math>\frac{1}{4}</math> S B T. A Fir, 12 ins. diam., bears S.50°E., 34 lks. dist. marked <math>\frac{1}{4}</math> S B T.</p> <p>58.00 Branch 2 lks., course N.80°W and descend on N slope.</p> <p>59.70 A boulder 15 ft. high and diam. on line.</p> <p>78.45 Foot of descent -700 and spring branch 1 lk. wide, course N. Ascend on N slope 25 ft. to</p> <p>80.60 The cor. to secs. 14, 15, 22 and 23.</p> <p>Land, mountainous, broken, rough.</p> <p>Heavy timber of Fir, Cedar, Pine and Matherone.</p> <p>Dense underbrush of small Fir, Vine Maple Hazel and Chinquapin.</p>