

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 33 S., R. 5 W.

CHAINS	<p>46.70 A Fir, 24 ins. diam. line tree marked with two notches on N and S sides.</p> <p>56.00 Top of divide +800 bears NW and SE. Descend on NE slope.</p> <p>68.00 A Fir, 30 ins. diam. line tree, marked with two notches on N and S sides.</p> <p>75.00 Foot of descent -400 and along E slope.</p> <p>80.00 Set a post 4 ft. long, 4 ins. sq. 24 ins. in the ground for cor. to secs. 2, 3, 10 and 11 marked T 33 S S 2 on NE., R 5 W S 11 on SE., S 10 on SW., and S 3 on NW faces with 5 notches on the S and 2 notches on E edges from which</p> <p style="padding-left: 40px;">A Fir, 18 ins. diam., bears N.36°E., 108 lks. dist. marked T 33 S R 5 W S 2 B T.</p> <p style="padding-left: 40px;">A Fir, 40 ins. diam., bears S.82°E., 61 lks. dist. marked T 33 S R 5 W S 11 B T.</p> <p style="padding-left: 40px;">A Fir, 10 ins. diam., bears S.21°30'W., 29 lks. dist. marked T 33 S R 5 W S 10 B T.</p> <p style="padding-left: 40px;">A Matherone, 14 ins. diam., bears N.54°W., 43 lks. dist. marked T 33 S R 5 W S 3 B T.</p> <p>Land, mountainous, broken, rough.</p> <p>Heavy timbered with Fir Cedar, and Pine.</p> <p>Underbrush of small Fir, Laurel, Matherone and Hazel.</p> <p>Soil, 2nd rate, with slate, gravel more especially the S <math>\frac{1}{2}</math> mile.</p> <p style="text-align: right;">June 7, 1894.</p>
	<p style="text-align: center;">South 89°10'E on a random line bet. secs. 2 and 11. Va 19°E.</p>
40.00	Set temp. $\frac{1}{4}$ sec. cor.
80.68	Intersect N and S line 37 lks. S. of cor. to secs. 1, 2, 11 and 12.