

## County Surveyor's Record, Douglas County, Oregon

24

## Subdivisions of T. 33 S., R. 5 W.

CHAINS

A Black Oak, 16 ins. diam., bears S.41\*E., 57 lks.  
dist. marked  $\frac{1}{2}$  S B T.

43.15 Ravine and spring branch 1 lk. wide, course S.70\*W  
ravine 75 ft. deep.

53.30 A Black Oak, 36 ins. diam., line tree, marked with  
2 notches on N and S sides.

56.00 Ravine, 30 ft. deep bears SW and ascend steep SW slope.

62.96 A Y. Pine, 24 ins. diam. line tree, marked with 2 notches  
on N and S sides, and summit of mountain spur, bears  
SW about 800 ft. above Coyote Creek.

Descend along W. slope.

77.50 Foot of descent -150 ft. and spring branch 2 lks. wide  
course SW.

Ascend steep S slope 60 ft. to

80.00 Set basaltic stone 12 x 10 x 6 ins. 8 ins. in the ground  
for cor. to secs. 15, 16, 21 and 22 marked with 3  
notches on the S and E edges from which

A live Oak, 4 ins. diam., bears N.35\*E., 48 lks.  
dist, marked T 33 S R 5 W S 15 B T.

A Matherone, 4 ins. diam., bears S.34\*E., 21 lks.  
dist, marked T 33 S R 5 W S 22 B T.

A Matherone, 5 ins. diam., bears S.55\*W., 19 lks.  
dist, marked T 33 S R 5 W S 21 B T.

A Matherone, 6 ins. diam., bears N.75\*W., 16 lks.  
dist, marked T 33 S R 5 W S 16 B T.

This corner is in a Matherone thicket.

Land, mountainous, broken rough and sloping to the SW.

Heavy timbered with Black Oak, Fir, Pine, Cedar and

Matherone.  $S\frac{1}{2}$  not dense underbrush. N 40.00 chs.

dense underbrush of small Fir and Oak, live Oak,

Hazel, Chinquapin, Chaparral and Matherone.

Soil 2nd rate, mostly.

June 12, 1894.