

25

Subdivisions of T 33. S., R. 5 W.

CHAINS	South 89°43'E on a random line between secs. 15 and 22. Va 19°E.
40.00	Set temp. $\frac{1}{4}$ sec. cor.
80.10	Intersect N and S line 10 lks. S of cor. to secs. 14, 15, 22 and 23. Thence I run N.89°47'W on a true line bet. secs. 15 and 22. Va 23°E.
	Ascend along N slope.
9.20	A Fir, 48 ins. diam. line tree, marked with 2 notches on E and W sides.
19.50	Deserted cabin bears S 5 lks. and leave timber through dense brush and ascend on divide bears E and W.
22.00	Top of ascent +200 ft. and descend on N slope.
24.64	A dead Fir, 24 ins. diam. line tree, marked with 2 notches on E and W sides and enter timber.
32.00	Foot of descent on N slope.
	Ascend on N slope.
40.05	Set basaltic stone 12 x 10 x 8 ins. 8 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on N side from which A Fir, 18 ins. diam., bears N.24°W., 16 lks. dist. marked $\frac{1}{4}$ S B T. A Fir, 12 ins. diam., bears S.36°30'E., 27 lks. dist. marked $\frac{1}{4}$ S B T. Continue ascending on N slope.
53.25	Commence descending rapidly on W slope.
69.68	A Fir, 24 ins. diam. line tree, marked with two notches on E and W sides.
74.50	Ravine bears S.70°W., and continue descending on SW slope.
80.10	The cor. to secs. 15, 16 21 and 22 -800 ft. Land, mountainous, broken, rough. Heavy timber of Fir, Pine Cedar and Matherone. Dense underbrush small Fir, Hazel, live Oak, Matherone and Chanquapin and blood root. Soil 3rd rate, gravelly, line mostly on N slope of divide.

-150

June 12, 1894.