

County Surveyor's Record, Douglas County, Oregon

31

Subdivisions of T. 33 S., R. 5 W.

CHAINS 5.90	A Fir, 36 ins. diam. line tree, marked with 2 notches on E and W sides.	
16.73	Top of ascent and mt. spur bears SE and descend gradually on S slope.	+200
31.64	A Fir, 40 ins. diam. line tree, marked with two notches on E and W sides.	
37.43	Begin to descent rapidly on W slope.	
40.12	A Fir, 8 ins. diam. which I marked $\frac{1}{4}$ S on N side for $\frac{1}{4}$ sec. cor. from which A Fir, 14 ins. diam., bears N.56*30'W, 55 lks. dist. marked $\frac{1}{4}$ S B T. A Black Oak, 10 ins. diam., bears S.65*W, 10 lks. dist, marked $\frac{1}{4}$ S B T. (No suitable tree NE nor SE of this cor.)	
46.83	Foot of descent -350 ft. and branch 2 lks. wide, course SE. Ascend toward ridge on E slope.	
49.48	Small ravine 10 ft. deep bears SE.	
55.43	Top of ridge +150 bears S. Descend on W slope.	
57.95	Foot of descent -50 and branch 3 lks. wide, course SW. Ascend on SE slope.	
62.60	A Matherone 12 ins. diam. line tree, marked with 2 notches on E and W sides.	
65.10	Top of ascent and mt. spur bears S. Descend on SW slope.	+200
76.30	Foot of descent -200 and branch 3 lks. wide, course SE. Ascend on SE slope 60 ft. to	
80.23	the cor. to secs. 3, 4, 9 and 10. Land, mountainous, broken, rough. Heavy timber of Fir, Matherone, Cedar, and Pine. Dense underbrush of small Fir, Hazel, Matherone. Soil, 2nd rate, gravelly.	

June 14, 1894.