

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions of T. 33 S., R. 5 W.

CHAINS		
	North 2'W between secs 3 and 4.	
	Va 19*E.	
	Descend 30 ft. on SE slope to	
3.65	Foot of descent and branch 3 lks. wide, course SE.	
	Ascend on steep S slope of a high mountain called	
	(Old Baldy).	
16.70	A Fir, 40 ins. diam. line tree, marked with 2 notches	
	on N and S sides.	
25.40	A Fir, 48 ins. diam. line tree marked with 2 notches	
	on N and S sides.	
30.00	Leave timber and ascend a mountain of rocks and brush.	
40.00	A stone 2 ft. x 2 ft. x 2 ft. which I marked $\frac{1}{4}$ on W side	
	for $\frac{1}{4}$ sec. cor. with a cross (x) at exact corner	
	point from which	
	A Live Oak, 5 ins. diam., bears N.15*30'W, 105 lks.	
	dist, marked $\frac{1}{4}$ S B T.	
	A Live Oak, 5 ins. diam., bears S.32*W., 83 lks.	
	dist, marked $\frac{1}{4}$ S B T.	
	No trees east of line.	
46.00	Top of mountain peak bears NE and SW.	+1500
	Descend on NW slope.	
46.50	Enter dense timber.	
53.00	A Fir, 60 ins. diam line tree, marked with 2 notches	
	on N and S sides.	
57.00	Foot of descent on NW slope -150 and ascend on W slope.	
70.00	Leave timber and ascend on W slope over rocks and	
	through brush to summit of divide bears N and S.10*E to	
79.74	Intersect N bdy. of Tp. Set temp. closing cor. Thence	
	I run on E slope E on N bdy. of Tp. 5.40 chs. to the	
	cor. to secs. 33 and 34 T 32 S R 5 W which I determined	
	by the SW bearing tree. The post and remaining three	
	bearing trees evidently have been destroyed by fire.	