

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions of T. 33 S., R. 5 W.

CHAINS 58.60	Foot of mountain and creek bottom.	-600
59.55	Creek, 10 lks. wide, course NW. Ascend gradually across "Hole in the Ground Mine".	
60.96	Wagon road bears SE and NW.	
61.66	East side of "Hole in the Ground" mine and through mine	
70.16	Top of S bank 40 ft. high of "Hole in the Ground" mine and descend 100 ft. on W slope to	+100
78.50	Foot of descent and creek, 8 lks. wide, course N. Ascend on E slope 75 ft. to	
80.66	The cor. to secs. 8, 9, 16 and 17. Land mountainous, broken, rough. Heavy timber of Fir, Matherone, Pine, Oak, and Cedar. Dense underbrush of small Fir, Matherone, Hazel, Buckhorn, Oak and Manzanita. Soil, 3rd rate, gravelly.	
	June 20, 1894.	
	North 3°W between secs. 8 and 9. Va 19°E.	
	Descend 75 ft. on steep NE slope to	
1.95	Foot of descent and creek 3 lks. wide, course NW. Across Wolf Creek bottom.	
6.90	Wagon Road E and W.	
7.85	Wolf Creek 25 lks. wide, course N.70°W.	
10.16	Trail bears E and W.	
12.82	Main wagon road leading to Wolf Creek Station and begin to ascend mountain.	
20.00	A cabin bears E 100 lks.	
21.00	Miners ditch bears N.20°W. and small garden of $\frac{1}{4}$ acre bears W 20 lks. and continue ascending on E side of canyon.	
28.92	A Cedar, 36 ins. diam. line tree, marked with two notches on N and S sides.	