

County Surveyor's Record, Douglas County, Oregon

38

Subdivisions of T. 33 S., R. 5 W.

CHAINS

East on a random line bet. secs. 4 and 9.

Va 19°E.

40.00 Set temp. $\frac{1}{4}$ sec. cor.

80.74 Intersect N and S line 37 lks. S of cor. to secs. 3,
4, 9 and 10.

Thence I run S.89°44'W on a true line bet. secs. 4 and 9.

Va 19°E.

Ascend E slope.

8.25 A Matherone 14 ins. diam. line tree, marked with two
notches on E and W sides.

8.75 Top of ridge +300 ft. bears N.10°W and S.10°E.

Descend on SW slope.

21.00 Foot of descent - 100 ft. and begin to ascend on a steep
high SE rocky slope.

21.00 Head of ravine bears S.20°E.

38.15 Live Oak, 8 ins. diam., line tree, marked with two
notches on E and W sides.

40.37 Set hard slate stone 14 x 12 x 6 ins. 10 ins. in the
ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on N side from which
A Fir, 24 ins. diam. bears N.45°E., 5 lks. dist.
marked $\frac{1}{4}$ S B T.

A Matherone, 6 ins. diam., bears S.4°W., 21 lks.
dist, marked $\frac{1}{4}$ S B T.

44.64 A Y. Pine, 24 ins. diam. line tree, marked with two
notches on E and W sides.

51.00 Top of ascent on SE slope +1000 ft. and mt. spur bears
SW. Descend on SW slope.

76.20 Head of ravine bears S.20°W.

77.80 Ridge bears S.30°W.

80.74 The cor. to secs. 4, 5, 8 and 9, 800 ft. below point
at 51.00 chs.

Land, mountainous, broken, rough, high.

Heavy timber of Fir, Oak, Pine, Matherone and Cedar.

Dense underbrush of Vine Maple, Hazel, live Oak, small
Fir, and Blood-root.

Soil 4th rate, gravelly and rocky.

June 20, 1894.