

## County Surveyor's Record, Douglas County, Oregon

43

## Subdivisions of T. 33 S., R. 5 W.

CHAINS

A Cedar, 26 ins. diam., bears S.59\*E., 46 lks. dist.  
marked  $\frac{1}{4}$  S B T.

A Fir, 16 ins. diam., bears S.67\*W., 16 lks. dist.  
marked  $\frac{1}{4}$  S B T.

(No N trees accessable).

43.62 Foot of descent -250 and creek 5 lks. wide, course N.  
Ascend mt. on NE slope.

48.03 A Fir, 60 ins. diam., line tree marked with 2 notches  
on E and W sides.

70.92 A Fir, 36 ins. diam., line tree, marked with two  
notches on E and W sides.

74.75 Summit of divide bears N and S a narrow back-bone like  
and about 700 ft. above creek at 43.62 chs.

Descend mt. on W slope 200 ft. to

80.17 The cor. to secs. 7, 8, 17 and 18.

Land, mountainous, broken, rough, sloping Northerly  
to Wolf Creek.

Heavy timber of Fir, Matherone, Oak, Pine and Cedar.

Dense underbrush of small Fir, Hazel, Vine Maple,  
Oak, and Matherone.

Soil 3rd rate, gravelly.

June 27, 1894.

N.89\*47' W on a random line bet. secs. 7 and 18.

Va 18\*50'E.

40.00 Set temp.  $\frac{1}{4}$  sec. cor.

74.70 Intersect W bdy. of Tp. 9 lks. S of cor. to secs. 7,  
12, 13 and 18 determined by bearing trees as the  
post for cor. was missing. At point for. cor. set  
a basaltic stone 18 x 10 x 8 ins. 12 ins. in the  
ground for cor. to secs. 7, 12, 13 and 18 T 33 S R's  
5 and 6 W marked with 4 notches on the S and 2 notches  
on the N edges from which