

County Surveyor's Record, Douglas County, Oregon

44

Subdivisions of T. 33 S., R. 5 W

CHAINS	<p>A Laurel, 10 ins. diam., bears N.71*W., 32 lks. dist. with well defined blazes partly grown over.</p> <p>A Laurel, 10 ins. diam., bears N.72*E., 35 lks. dist. with well defined blazes partly grown over.</p> <p>A Laurel, 12 ins. diam., bears S.44*E., 7 lks. dist. with well defined blazes partly grown over.</p> <p>A Redwood, 16 ins. diam., bears S.70*W., 55 lks. dist, with well defined blazes partly grown over.</p> <p>Thence I run S.89*45'E. on a true line between secs. 7 and 18.</p> <p style="text-align: right;">Va 19*E.</p> <p>Ascend on NW slope.</p> <p>18.35 Ravine, 20 ft. deep, course NW.</p> <p>23.00 Begin to ascend now on N slope of mt.</p> <p>26.42 Ravine, 50 ft. deep bears N, and along steep N slope.</p> <p>34.00 Top of ascent on N slope +400 and begin to descend on steep E slope.</p> <p>34.70 Set hard slate stone 22 x 10 x 5 ins. 17 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on N side from which</p> <p style="padding-left: 40px;">A Matherone, 12 ins. diam., bears N.1*E., 6 lks. dist, marked $\frac{1}{4}$ S B T.</p> <p style="padding-left: 40px;">A Fir, 9 ins. diam., bears S.38*W., 16 lks. dist, marked $\frac{1}{4}$ S B T.</p> <p>47.20 Foot of steep E slope -500 ft. and creek 8 lks. wide, course N.10*W.</p> <p>Ascend steep W slope.</p> <p>49.27 A Fir, 24 ins. diam., on line, marked with 2 notches on E and W sides.</p> <p>63.50 A Fir, 30 ins. diam. line tree, marked with 2 notches on E and W sides.</p> <p>74,70 The cor. to secs. 7, 8, 17 and 18. +600</p> <p style="padding-left: 40px;">Land, mountainous, broken, rough, all drained by Wolf Creek.</p> <p style="padding-left: 40px;">Heavy timber of Oak, Cedar, Fir, Matherone and Pine.</p> <p style="padding-left: 40px;">Dense underbrush of Hazel, small Fir, Oak, Matherone and Blood-root.</p>
--------	--