

County Surveyor's Record, Douglas County, Oregon

415

Subdivisions of T. 33 S., R. 5 W.

CHAINS 45.87	A Y. Pine, 31 lks. in circumference, line tree marked with two notches on E and W sides.
46.00	Summit of mt. spur +700 bears S.30°E. Descend on steep SW slope.
59.00	Ravine 50 ft. deep and spring branch 2 lks. wide, bears SW.
65.90	Top of bluff, 50 ft. high.
66.30	Foot of steep descent -600 and ravine bears S. Ascend steep SE slope.
71.40	Top of steep ascent and ridge +150 ft. bears S. Descend 150 ft. on steep SW slope to
77.50	Foot of descent and branch 3 lks. wide, course S.10°W.
79.30	Ravine 20 ft. deep bears S. Ascend steep SE slope 40 ft. to The cor. to secs. 5, 6, 7, and 8. Land, mountainous, broken, rough, high and drained by Wolf Creek. Heavy timber of Oak, Fir, Pine, Matherone, Cedar and mountain Mahogany. Dense undergrowth of Oak, Matherone and Fir. Soil 3rd rate, gravelly.

June 28, 1894.

N.89°45'W on a random line bet. secs. 6 and 7.

Va 18°50'E.

40.00	Set temp. $\frac{1}{4}$ sec. cor.
74.66	Intersect W bdy. of Tp. 16 lks. S of cor. to secs. 1, 6, 7 and 12, which is a post greatly decayed and partly burnt, therefore I set a post, 4 ft. long, 4 ins. sq. 24 ins. in the ground for cor. to secs. 1, 6, 7 and 12, Tps. 33 S R 5 and 6 W marked T 33 S S 6 on NE., R 5 W S 7 on SE., R 6 W S 12 on SW