

## County Surveyor's Record, Douglas County, Oregon

16

## Subdivisions of T. 33 S., R. 5 W.

CHAINS	<p>and S 1 on NW sides with 5 notches on the S and 1 notch on the N edges from which</p> <p>A B. Oak, 14 ins. diam., bears N.53*W., 108 lks. dist, with well defined blazes.</p> <p>A B. Oak, 24 ins. diam., bears S.53*E., 44 lks. dist, with well defined blazes.</p> <p>A Redwood, 14 ins. diam., bears N.51*E., 33 lks. dist, with well defined blazes.</p> <p>The NW tree being broken down, I establish</p> <p>A Matherone, 24 ins. diam., bears S.85*W., 20 lks. dist marked T 35 S R 6 W S 12 B T.</p> <p>Thence I run S.89*38'E on a true line bet. secs. 6 and 7.</p> <p style="text-align: right;">Va 18*10'E.</p> <p>Along about level on SE slope to</p> <p>6.70 Descend 75 ft. on steep descent to</p> <p>8.65 Foot of descent and creek 5 lks. wide, course SW.</p> <p>Ascend rapidly on steep NW mt. slope.</p> <p>17.20 A Fir, 36 ins. diam. line tree, marked with 2 notches on E and W sides.</p> <p>18.65 Ravine, 50 ft. deep and spring branch 1 lk. wide, course NW.</p> <p>34.66 Set a hard slate stone 18 x 16 x 4 ins. 12 ins. in the ground for <math>\frac{1}{4}</math> sec. cor. marked <math>\frac{1}{4}</math> on N side from which</p> <p style="padding-left: 40px;">A B. Oak, 14 ins. diam., bears N.26*E., 5 lks. dist. marked <math>\frac{1}{4}</math> S B T.</p> <p style="padding-left: 40px;">A B. Oak, 6 ins. diam., bears S.30*W., 11 lks. dist. marked <math>\frac{1}{4}</math> S B T.</p> <p>39.05 A mt. ridge, bears SW and NE and now ascend on S slope of mt.</p> <p>41.00 Top of ascent on S slope +500 ft. above creek at 8.65 chs. and descend on S slope.</p> <p>45.46 Mt. spur bears S.40*E., and descend on SE slope.</p> <p>48.11 A B. Oak, 16 ins. diam. line tree marked with 2 notches on E and W sides.</p>
--------	---