

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 33 S., R 7 W.

CHAINS

53.00 A creek, 15 lks. wide, Course S.30*W., ascend.
 71.50 Top of spur, Course SE., descend.
 76.00 A creek, 6 lks. wide, Course SE.
 80.00 Marked a Fir tree T 33 S R 7 W S 14 on NE., S 23 on SE.,
 S 22 on the SW. and S 15 on NW.; also 3 notches on S.
 and 2 notches on E. angles of same for the corner to
 secs. 14, 15, 22 and 23, from which

A Maple, 10 ins. diam., bears N.20*E., 22 lks. dist.,
 Marked T 33 S R 7 W S 14 B T and

A Live Oak, 12 ins. diam., bears S.70*E., 17 lks.
 dist., Marked T 33 S R 7 W S 23 B T and

A Fir, 30 ins. diam., bears S.5*W., 61 lks. dist.,
 Marked T 33 S R 7 W S 22 B T.

A Live Oak, 12 ins. diam., bears N.70*W., 16 lks.
 dist., Marked T 33 S R 7 W S 15 B T.

Land, mountainous and broken.
 Soil, rocky, third rate.
 Timber, poor, chiefly Fir, Oak, Laurel and Pine.
 Undergrowth, same.

February 17, 1882.

East on Random line between secs. 14 and 23.

Va. 17*30'E.

3:50 Steep descent.
 21.25 A creek, 15 lks. wide, Course S., steep ascent.
 40.00 Set temporary $\frac{1}{4}$ sec. corner.
 54.00 Top of spur, Course NW. Along steep mountain side, N.
 80.20 Intersect N. and S. line 75 lks. south of corner to secs.
 13, 14, 23 and 24, thence
 S.89*28'W. on true line between secs. 14 and 23.
 40:10 Set an Oak post, 3 feet long, 4 ins. square, 20 ins. in
 the ground, marked $\frac{1}{4}$ S on N. side, for the $\frac{1}{4}$ sec.
 corner, from which