

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 33 S., R 7 W.

CHAINS

SE., S 21 on SW. and S 16 on NW. faces. Also 3 notches on S. and E. angles of same for the corner to secs. 15, 16, 21 and 22, from which

A Fir, 7 feet (?) diam., bears N.62*E., 21 lks. dist.

Marked T 33 S R 7 W S 15 B T.

An Alder, 15 ins. diam., bears S.44*E., 53 lks. dist.

Marked T 33 S R 7 W S 22 B T.

A Maple, 8 ins. diam., bears S.65*W., 47 lks. dist.

Marked T 33 S R 7 W S 21 B T.

A Dogwood, 4 ins. diam., bears N.12*W., 17 lks. dist.

Marked T 33 S R 7 S W 16 B T.

Land, mountainous, broken.

Soil, third rate.

Timber, chiefly, Fir, Oak, Laurel and Cedar.

Undergrowth, same.

East on Random line between secs. 15 and 22.

Va. 17*30'E.

11.90 A creek, 12 lks. wide, Course SE.

25.08 A creek, 12 lks. wide, Course S. Steep ascent.

40.00 Set temporary 1/4 sec. corner.

51.25 Top of ridge, Course SW. Broken ridges.

80.50 Intersect 26 lks. S. of corner to secs. 14, 15, 22 and 23, thence

S.89*49'W. on true line between secs. 15 and 22.

Va. Same

40.25 Set a Laurel post, 3 feet long, 3 ins. square, 20 ins. in the ground, marked 1/4 S on N. side for the 1/4 sec. corner, from which

A Live Oak, 5 ins. diam., bears S.52*W., 13 lks. dist.

Marked 1/4 S B T and

A Live Oak, 5 ins. diam., bears N.24*W., 21 lks. dist.

Marked 1/4 S B T.