

Subdivisions of T. 33 S., R. 7 W.

CHAINS

- 80.50 To the cor. to secs. 15, 16, 21 and 22.  
 Land, mountaionous; soil, third rate.  
 Timber, poor, chiefly fir, oak, laurel and pine.  
 Undergrowth, same.
- 
- North, bet. secs. 15 and 16.  
 Va. 17°30'E.
- 0.80 A creek, 15 lks. wide, course SE; steep ascent.
- 20.00 Top of spur, course S.30°E; moderate descent.
- 40.00 Set laurel post, 40 ins. long, 3 ins. square, 18 ins. in the ground, marked  $\frac{1}{4}$  S on W side for the  $\frac{1}{4}$  sec. cor. from which  
     A fir, 22 ins. diam., bears S.53°E., 26 lks. dist. marked  $\frac{1}{4}$  S B T.  
     A fir, 10 ins. diam., bears S.70°W., 31 lks. dist. marked  $\frac{1}{4}$  S B T.
- 60.08 A creek, 12 lks. wide, course SE; steep ascent.
- 80.00 Set a laurel post, 4 ft. long, 4 ins. square, 2 ft. in the ground, marked T 33 S R 7 W S 10 on NE., S 15 on SE., S 16 on SW., and S 9 on NW. faces; also 4 notches on S and 3 notches on E angles of same for the cor. to secs. 9, 10, 15 and 16, from which  
     A Laurel, 12 ins. diam., bears N.50°E., 15 lks. dist. marked T 33 S R 7 W S 10 B T.  
     A Laurel, 5 ins. diam., bears S.22°E., 44 lks. dist. marked T 33 S R 7 W S 15 B T.  
     A fir, 46 ins. diam., bears S.10°W., 28 lks. dist. marked T 33 S R 7 W S 16 B T.  
     A Laurel, 8 ins. diam., bears N.12°W., 40 lks. dist. marked T 33 S R 7 W S 9 B T.
- Land, mountaionous, broken; soil, third rate.  
 Timber, fir, oak, laurel and cedar.  
 Undergrowth, same.