

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions of T. 33 S., R. 7 W.

## CHAINS

Undergrowth; small firs, live oak, burr oaks, wax myrtles.  
Mountainous or heavily timbered land or covered with  
dense undergrowth, 80.00 chs.

N.89°54'E., on a random line bet. secs. 9 and 16.

40.00 Set temp.  $\frac{1}{4}$  sec. cor.

79.73 Intersect N. and S. line, 49 lks. N. of cor. of secs. 9,  
10, 15, and 16, which having disappeared, I restore  
the cor. by setting a fir post, 3 ft. long, 4 ins. sq.  
24 ins. in the ground, for cor. of secs. 9, 10, 15 and  
16, mkd. T 33 S S 10 on NE., R 7 W S 15 on SE., 1 S S  
16 on SW., and S 9 on NW. faces, with 4 notches on S.  
and 3 notches on E. edges, and witnessed as described  
by the Surveyor General.

Thence I run

N.89°48'W., on true line bet. secs. 9 and 16.

Desc. S. slope of mountain, covered with a dense under-  
growth of small firs, laurel, live and burr oaks and  
manzanita.

7.40 A stream, 2 lks. wide, course S; continue descent.

39.86 Set a granite stone, 16x8x8 ins., 11 ins. in the ground,  
for  $\frac{1}{4}$  sec. cor. mkd.  $\frac{1}{4}$  on N. face, from which,

A laurel, 6 ins. diam., bears S.28°E., 15 lks. dist.  
marked  $\frac{1}{4}$  S 16 B T

A laurel, 8 ins. diam., bears N.73°W., 16 lks. dist.  
marked  $\frac{1}{4}$  S 9 B T

Continue steep ascent of SE. mountain slope, cor. stands  
150 ft. above stream.

47.00 A rocky mountain spur, bears N. and S., 125 ft. above sec.  
cor., continue steep ascent of rocky S. slope, covered  
with loose shell rock.

73.70 Ascent, changes to E. mountain slope.

79.73 The cor. of secs. 8, 9, 16, 17, 600 ft. above  $\frac{1}{4}$  sec. cor.