

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 33 S., R. 7 W.

CHAINS

trees remain, I mark a Fir, 16 ins. diam., bears N.11 $\frac{1}{2}$ *E.,
84 lks. dist., Marked T 32 S R 7 W S 32 B T.

A Fir, 18 ins. diam., bears N.72*W., 110 lks. dist.,
Marked T 32 S R 7 W S 31 B T.

The third original B T is still standing.

At the point of intersection, I set a granite stone,
18 x 12 x 6 ins., 12 ins. in the ground for closing
corner of secs. 5 and 6 marked C C on S., with 5
grooves on E., and 1 groove on W. faces, from which

A Fir, 15 ins. diam., bears S.57*W., 100 lks. dist.,
Marked T 33 S R 7 W S 6 B T.

A Sugar Pine, 32 ins. diam., bears S.81*E., 78 lks.
dist., Marked T 33 S R 7 W S 5 B T.

Land, mountainous.

Soil, gravelly, third rate.

Timber, Fir, Yellow and Sugar Pine, Cedar, Laurel,

Undergrowth, poison Laurel, small Live Oak.

Mountainous or heavily timbered land or covered by dense
undergrowth. 83.56 chs. and connecting line 9.15 chs.

August 5, 1901.

General Description

The part of this Township now surveyed consists of the
top of Mount Reuben, forming the ridge, dividing the
waters of the Umpqua and Rogue Rivers. It is all
mountainous, is entirely covered by large Fir timber
and large Sugar Pine timber, to remove which will ve
very expensive. The soil is mostly very thin, except
in some very narrow creek bottoms. There is abundance
of water in streams and springs the year round. There
are plenty indications of the presence of gold, and