

County Surveyor's Record, Douglas County, Oregon

T. 33 S., R. 7 W.
General Description

CHAINS

plenty of prospect holes of miners can be found, but no big strikes have occurred.

There are no settlers in this part of the Township, and there is no inducement for settlers, unless a discovery of a rich gold mine will make a boom.

Oscar F. Thiel.

U. S. Deputy Surveyor.

Resurvey of West Boundary of T. 33 S., R. 7 W.
As executed by Norman D. Price, U. S. Surveyor and
Ira F. Shaffner, U.S. Transitman
Under instructions dated September 22, 1916.

From the cor. to Sec. 18 only.

Thence N.0*27'E.

40.14 The cor. established for secs. 7, 12, 13 and 18, which is a granite stone, 12 x 10 x 6 ins. above ground, firmly set, mkd. and witnessed as described by the surveyor general.

Hereafter this cor. will refer to secs. 7 and 18 only.

Obliterate markings on bearing trees referring to secs.

W. of line.

Land, mountainous.

Soil, loose, coarse, rocky loam; third rate.

Timber, Fir, Pine, Live Oak, Madrona, Cedar and Yew.

Undergrowth, Snowbrush, Lilac, Live Oak, Chinquapin and Buckhorn.

N. 0*26'E., on W. bdy. of sec. 7.

Asc. 760 ft. over SW. slope, through heavy green timber and dense undergrowth.

24.40 Spur, slopes SE., desc. 205 ft. over NE. slope.

32.10 Branch, 1 lk. wide, course SE., asc. 185 ft. over SW. slope to the old $\frac{1}{4}$ sec. cor.

37.98 Set a limestone, 18 x 18 x 10 ins., 14 ins. in the ground for a cor. of sec. 12, mkd. $\frac{1}{4}$ on W. face; from which a Pine, 36 ins. diam., bears S. 22*W., 120 lks. dist mkd. $\frac{1}{4}$ S 12 B T.