

County Surveyor's Record, Douglas County, Oregon

Resurvey of the West Boundary of T. 33 S., R. 7 W.

CHAINS

Alongside of post,

Set a limestone 20x14x10 ins., 15 ins. in the ground, mkd. with 6 grooves on E., S. and W. faces and CC on S face.

Land, mountainous.

Soil, loose, coarse, rocky loam; third rate.

Timber, Fir, Pine, Madrona and Cedar.

Undergrowth, Chinquapin, Buckhorn, Live Oak, and Madrona.