

County Surveyor's Record, Douglas County, Oregon

10

Subdivisions of T. 33 S., R. 8 W.

CHAINS

A Fir, 8 ins. diam., bears N.16 $\frac{1}{2}$ *W., 22 lks. dist.,
mkd. T 33 S R 8 W S 2 B T.

Land, mountainous.

Soil, loose, coarse, rocky loam, 3rd rate.

Timber, Pine, Fir, Madrona, and Live Oak.

Undergrowth, Lilac, Madrona, Chinquapin, Live Oak,

Buckhorn and Manzanita.

S.89*47'E., on random line between secs. 1 and 12.

40.00 Set temp. $\frac{1}{4}$ sec. cor.

82.66 Intersect E. bdy. of Tp., 9 lks. N. of; the cor. of secs.
1 and 12.

Thence

N.89*43'W., on a true line between secs. 1 and 12.

Desc. 90 ft. over SW. slope, through heavy green timber
and dense undergrowth.

11.90 Ravine, course S., asc. 445 ft. over SE. slope to ridge.

20.05 Road, bears NE. and SW.

37.10 Ridge, bears NE. and SW., desc. 130 ft. over broken
NW. slope.

42.66 Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in
the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.

S1
 $\frac{1}{4}$ -----
S12
1919

from which

A Fir, 30 ins. diam., bears N.13*E., 38 lks. dist.,
mkd. $\frac{1}{4}$ S 1 B T.

A Fir, 36 ins. diam., bears S.7*E., 40 lks. dist.,
mkd. $\frac{1}{4}$ S 12 B T.

Desc. 910 ft. over broken NW. slope.

79.30 Head of ravine, course NW., thence over N. slope.

82.66 The cor. of secs. 1, 2, 11 and 12.

Land, mountainous.

Soil, loose, coarse, rocky loam, 3rd rate.