

South Boundary of T. 24 S., R. 1 E., W. M.

CHAINS		
52.25	Creek, 3 lks. wide, course South.	-250
	Ascend	
72.00	Top of ridge, sloping S.	+100
	Descend.	
80.00	Set basalt stone 18x12x8 ins. 16 ins. in the ground on	
	hillside, sloping gradually to the South, for cor. to	
	secs. 32, 33, 4 and 5, marked with 2 notches on the W.	
	and 4 notches on the E. sides, from which	
	A Hemlock, 4 ins. diam., bears N.27*E., 18 lks. dist.,	
	marked T 24 S R 1 E S 33 B T.	
	A Silver Fir, 14 ins. diam., bears S.81*E., 43 lks.	
	dist., marked T 25 S R 1 E S 4 B T.	
	A Red Fir, 30 ins. diam., bears S.57*W., 23 lks.	
	dist., marked T 25 S R 1 E S 5 B T.	
	A Silver Fir, 14 ins. diam., bears N.34*W., 34 lks.	
	dist., marked T 24 S R 1 E S 32 B T.	
	Land, mountainous. 80.00 chs.	
	Soil, Rocky, 3rd and 4th rate.	
	Heavily timbered with Red and Silver Fir, Hemlock, Pine	
	and Cedar. 80.00 chs.	
	Dense undergrowth of Vine Maple, Rhododendron, Fir and	
	Hemlock. 80.00 chs.	
	East, on true line between Secs. 33 and 4.	
	Va. 20*30'E.	
19.75	Dry bed of stream, 4 lks. wide, course SE.	
	Pass over spur.	
40.00	Set sandstone 14x12x3 ins., 10 ins. in the ground on	
	steep, rocky hillside, sloping NE., for $\frac{1}{2}$ Sec. cor.	
	marked $\frac{1}{2}$ on the N side, from which	
	A Fir, 10 ins. diam., bears S.28*W., 28 lks. dist.,	
	marked $\frac{1}{2}$ S B T.	
	A Fir, 10 ins. diam., bears N.13*E., 42 lks. dist.,	
	marked $\frac{1}{2}$ S B T.	