

South Boundary of T. 24 S., R. 1 E.

CHAINS 40.00	<p>Set sandstone, 13x8x6 ins., 8 ins. in the ground, on steep rocky hillside, sloping SW., for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on N. side, from which</p> <p style="padding-left: 40px;">A Fir, 8 ins. diam., bears North, 12 lks. dist., marked $\frac{1}{4}$ S B T.</p> <p style="padding-left: 40px;">A Fir, 6 ins. diam., bears S.30*E., 16 lks. dist., marked $\frac{1}{4}$ S B T.</p> <p style="text-align: right;">Va. 22*30'E.</p>	
47.50	<p>Top of rocky ridge, course N. and S.</p> <p>Gradual descent.</p>	+300
80.00	<p>Set basalt stone, 14x8x8 ins., 10 ins. in the ground, on hillside, sloping SE., for cor. to Secs. 34, 35, 2 and 3, marked with 4 notches on the W. and 2 notches on the East faces, from which</p> <p style="padding-left: 40px;">A Cedar, 12 ins. diam., bears N.75*E., 36 lks. dist., marked T 24 S R 1 E S 35 B T.</p> <p style="padding-left: 40px;">A Fir, 8 ins. diam., bears S.20*E., 30 lks. dist., marked T 25 S R 1 E S 2 B T.</p> <p style="padding-left: 40px;">A Fir, 36 ins. diam., bears S.21*45'W., 35 lks. dist., marked T 25 S R 1 E S 3 B T.</p> <p style="padding-left: 40px;">A Cedar, 4 ins. diam., bears N.41*W., 64 lks. dist., marked T 24 S R 1 E S 34 B T.</p> <p>Land, mountainous. 80.00 chs.</p> <p>Soil, 2nd and 3rd rate.</p> <p>Timber, Fir, Pine and Cedar.</p> <p>Dense undergrowth of Vine Maple, Fir, Hemlock, Lilac, Mountainbalm and Chinquapin. 80.00 chs.</p> <p style="text-align: right;">April 6, 1898.</p>	-250
	<p>East, between Secs. 35 and 2.</p> <p style="text-align: right;">Va. 20*E.</p> <p>Descend.</p>	
0.65	<p>A thick bark Cedar, 60 ins. diam. A line tree marked with 2 notches on the E. and W. sides.</p>	