

County Surveyor's Record, Douglas County, Oregon

Retracement and Dependent Resurvey
of the Willamette Meridian, through T. 25 S.

CHAINS	<p>A fir, 16 ins. diam., bears N.29*E., 30 lks dist., marked $\frac{1}{4}$ S 6 B T.</p> <p>A fir, 24 ins. diam., bears S.42*E., 36 lks. dist., marked $\frac{1}{4}$ S 6 B T.</p> <p>40.48 The $\frac{1}{4}$ sec. cor. established for secs. 1 and 6, which is a badly decayed madrona post with marks illegible. I now change this cor. to refer to sec. 1 only. In place of the decayed post Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, for $\frac{1}{4}$ sec. cor. of sec. 1 only , with brass cap marked</p> <div style="text-align: center;"> $\frac{1}{4}$ S 1 1927 </div> <p style="text-align: right;">from which</p> <p>A fir, 30 ins. diam., bears S.50*E., 96 lks. dist., old B.T., the marks on which I now destroy.</p> <p>A chinquapin, 14 ins. diam., bears S.35*W., 23 lks. dist., old B.T., with marks grown over.</p> <p>A pine, 8 ins. diam., bears N.62*W., 22 lks. dist., marked $\frac{1}{4}$ S 1 B T. (new B.T.)</p> <p>Thence N.0*24*W.</p> <p>7.75 Spur, 75 ft. above $\frac{1}{4}$ sec. cor., slopes W.; desc. 125 ft. over NW. slope.</p> <p>13.90 Creek, 4 lks. wide, course W.</p> <p>14.10 Creek, 1 lk. wide, course SW.; asc. 150 ft. over SW. slope.</p> <p>29.10 Spur, slopes NW.; desc. 160 ft. over NE. slope.</p> <p>40.26 The cor. of Tps. 24 and 25 S., Rs. 1 E. and 1 W., which is a pine post, 4 ins. sq., extending $2\frac{1}{2}$ ft. above ground, firmly set, marked</p> <div style="text-align: center;"> <p>T 24 S S 31 on NE.,</p> <p>R 1 E S 6 on SE.,</p> <p>T 25 S S 1 on SW., and</p> <p>R 1 W S 36 on NW. faces, with 6 notches</p> </div>
--------	--