

County Surveyor's Record, Douglas County, Oregon

Retracement and Dependent Resurvey
of South Boundary, T. 24 S., R. 1 E.

CHAINS

Land, mountainous.

Soil, coarse rocky loam; 2nd and 3rd rate.

Timber, fir, cedar, pine and madrona.

Undergrowth, vine maple, rhododendron, hazel, manzanita
and oak.

Thence

S.89°42'W., on a true line, on S. bdy. of sec. 33.

Asc. 300 ft. over SE. slope, through heavy timber and
dense undergrowth.

11.00 Spur, slopes SE.; desc. 80 ft. over S. slope.

14.45 Cross low saddle on spur, bears NE. and SW. and continue
desc. along N. slope.

19.15 Dry ravine, course NE.; asc. 250 ft. over E. slope.

29.70 Spur, slopes NE.; desc. along N. slope.

32.30 Asc. NE. slope, 95 ft.

38.87 Mid point on N. bdy. of sec. 4, determined as hereinafter
set forth.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in
the ground, for $\frac{1}{4}$ sec. cor. of sec. 4 only, with brass
cap marked

$\frac{1}{4}$ S4
1928

from which

A fir, 6 ins. diam., bears S.19°W., 26 lks. dist.
marked $\frac{1}{4}$ S 4 B T.

A fir, 20 ins. diam., bears S.83°W., 30 lks. dist.
marked $\frac{1}{4}$ S 4 B T.

40.35 The $\frac{1}{4}$ sec. cor. established for secs. 4 and 33, which is
a sandstone, 6x12x4 ins. above ground, firmly set,
marked $\frac{1}{4}$ on N. face.

I now change this cor. to refer to sec. 33 only.

Re-mark the stone $\frac{1}{4}$ S 33 on N. face; from which