

County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 25 S., R. 1 E.

CHAINS

A hemlock, 18 ins. diam., bears N.17*E., 55 lks.
dist., marked $\frac{1}{4}$ S 36 B T.

A Fir, 6 ins. diam., bears S.79*W., 21 lks.
dist., marked $\frac{1}{4}$ S 35 B T.

Desc. 425 ft. over NW. slope.

52.50 Creek, 4 lks. wide, course NE.; thence desc. 180 ft.
along broken E. slope.

64.60 Creek, 2 lks. wide, course NE.

80.00 A fir, 24 ins. diam.; for cor. of secs. 25, 26, 35 and
36, I mark

T 25 S S 25 on NE.,

R 1 E S 36 on SE.,

S 35 on SW., and

S 26 on NW. side; from which

A fir, 50 ins. diam., bears N.68*E., 11 lks.
dist., marked T 25 S R 1 E S 25 B T.

A fir, 36 ins. diam., bears S.35*E., 76 lks.
dist., marked T 25 S R 1 E S 36 B T.

A fir, 48 ins. diam., bears S.45*W., 65 lks.
dist., marked T 25 S R 1 E S 35 B T.

A hemlock, 16 ins. diam., bears N.66*W., 65 lks.
dist., marked T 25 S R 1 E S 26 B T.

Land, mountainous.

Soil, coarse rocky loam; 2nd and 3rd rate.

Timber, fir, cedar, hemlock and pine.

Undergrowth, vine maple, rhododendron, and hazel.

East, on a random line, bet. secs. 25 and 36.

40.00 Set temp. $\frac{1}{4}$ sec. cor.

79.96 Intersect E. bdy of the Tp., 23 lks. N. of the cor.
of secs. 25, 30, 31 and 36, hereinbefore described.