

County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 25 S., R. 1 E.

CHAINS

A cedar, 16 ins. diam., bears S.35*W., 42 lks. dist., marked 1/4 S 22 B T.

Asc. 240 ft. over SE. slope.

46.00 Continue asc. along broken E. slope.

58.00 Dry ravine, course E.

65.00 Desc. 100 ft. over N. slope.

71.50 Dry ravine, course NE.; thence along E. slope.

73.00 Desc. 65 ft. over NE. slope.

80.00 Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for cor. of secs. 14, 15, 22 and 23, with brass cap marked

T25S	R1E
S15	S14
S22	S23
1927	

from which

A fir, 8 ins. diam., bears N.22 1/2 *E., 38 lks. dist., marked T 25 S R 1 E S 14 B T.

A hemlock, 8 ins. diam., bears S.47 *E., 51 lks. dist., marked T 25 S R 1 E S 23 B T.

A hemlock, 6 ins. diam., bears S.46 *W., 40 lks. dist., marked T 25 S R 1 E S 22 B T.

A fir, 16 ins. diam., bears N.30 *W., 73 lks. dist., marked T 25 S R 1 E S 15 B T.

Land, mountainous.

Soil, coarse rocky loam; 2nd and 3rd rate.

Timber, fir, hemlock, cedar and pine.

Undergrowth, vine maple, hazel, rhododendron, willow and manzanita.

S.89*58'E., on a random line, bet. secs. 14 and 23.

40.00 Set temp. 1/4 sec. cor.

79.66 Intersect N. and S. line, 30 lks. N. of the cor. of secs. 13, 14, 23 and 24.