

County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 25 S., R. 1 E.

CHAINS

40.00 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked.



from which.


A fir, 8 ins. diam., bears N.33 $\frac{1}{2}$ *E., 43 lks. dist., marked $\frac{1}{4}$ S 34 B T.

A fir, 12 ins. diam., bears N.36*W., 15 lks. dist., marked $\frac{1}{4}$ S 33 B T.

Desc. 425 ft. to sec. cor., along broken E. slope.

72.00 Continue desc. over N. slope.

80.00 Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for cor. of secs. 27, 28, 33 and 34, with brass cap marked



from which.

A hemlock, 10 ins. diam., bears N.18*E., 57 lks. dist., marked T 25 S R 1 E S 27 B T.

A hemlock, 12 ins. diam., bears S.22*E., 53 lks. dist., marked T 25 S R 1 E S 34 B T.

A fir, 18 ins. diam., bears S.34*W., 72 lks. dist., marked T 25 S R 1 E S 33 B T.

A fir, 24 ins. diam., bears N.41*W., 85 lks. dist., marked T 25 S R 1 E S 28 B T.

Land, mountainous.

Soil, coarse rocky loam; 2nd and 3rd rate.

Timber, fir, hemlock, cedar and pine.

Undergrowth, vine maple, hazel and rhododendron.