

County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 25 S., R. 1 E.

CHAINS	<p>Asc. 15 ft. to</p> <p>43.90 Spur, slopes SE.; desc. 60 ft. over NE. slope.</p> <p>46.75 Dry ravine, course SE.; asc. 65 ft. over S. slope.</p> <p>57.15 Spur, slopes E.; desc. 85 ft. over NE. slope.</p> <p>62.00 Asc. gradually.</p> <p>79.20 Creek, 3 lks. wide, course SE.</p> <p>80.00 A fir, 28 ins. diam., for cor. of secs. 16, 17, 20 and 21, I mark</p> <p style="text-align: center;">T 25 S S 16 on NE., R 1 E S 21 on SE., S 20 on SW., and S 17 on NW. side; from which</p> <p>A hemlock, 18 ins. diam., bears N.31*E., 24 lks. dist., marked T 25 S R 1 E S 16 B T.</p> <p>A hemlock, 10 ins. diam., bears S.57*E., 18 lks. dist., marked T 25 S R 1 E S 21 B T.</p> <p>A cedar, 14 ins. diam., bears S.61*W., 36 lks. dist., marked T 25 S R 1 E S 20 B T.</p> <p>A cedar, 24 ins. diam., bears N.45*W., 34 lks. dist., marked T 25 S R 1 E S 17 B T.</p> <p>Land, mountainous.</p> <p>Soil, coarse rocky loam; 2nd and 3rd rate.</p> <p>Timber, fir, hemlock, cedar and pine.</p> <p>Undergrowth, vine maple, rhododendron, hazel and willow.</p> <hr/> <p>S.89*55'E., on a random line, bet. secs. 16 and 21.</p> <p>40.00 Set temp. $\frac{1}{4}$ sec. cor.</p> <p>80.40 Intersect N. and S. line, 19 lks. N. of the cor. of secs. 15, 16, 21 and 22.</p> <p>Thence</p> <p>N.89*47'W., on a true line, bet. secs. 16 and 21.</p> <p>Asc. 500 ft. over general E. slope, through heavy timber and dense undergrowth.</p>
--------	--