

County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 25 S., R. 1 E.

CHAINS

Across small point, through heavy timber and dense undergrowth.

- 0.75 Creek, 3 lks. wide, course SE.; asc. 455 ft. over SW. slope.
- 27.45 Spur, slopes SE.; desc. 197 ft. over N. slope.
- 37.50 Thence along E. slope.
- 40.00 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked

$$\frac{1}{4}$$

S8	S9
1927	

from which

A hemlock, 10 ins. diam., bears N.22*E., 33 lks. dist., marked $\frac{1}{4}$ S 9 B T.

A fir, 10 ins. diam., bears N.21*W., 41 lks. dist., marked $\frac{1}{4}$ S 8 B T.

- 45.30 Desc. 800 ft. over steep NE. slope.
- 54.75 Bottom of steep descent; thence across bench sloping gradually to east.
- 66.80 Leave bench; desc. steep NE. slope.
- 80.00 The point for the sec. cor. falls at the S. edge of a creek, 8 lks. wide, course E.
- 80.58 Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for witness cor. to the cor. of secs. 4, 5, 8 and 9, with brass cap marked

T25S	R1E
S5	S4
S8	S9
WC	
1927	

from which

A cedar, 10 ins. diam., bears N.21*E., 55 lks. dist., marked W C T 25 S R 1 E S 4 B T.