

## County Surveyor's Record, Douglas County, Oregon

## Subdivision of T. 25 S., R. 1 E.

## CHAINS

42.00 Continue asc. over SE. slope.

54.30 Dry ravine, course SE.; continue asc. over NE. slope.

61.60 Spur, slopes S.; desc. 400 ft. over SW. slope.

72.60 Creek, 1 lk. wide, course S.; asc. 100 ft. over SE. slope.

75.00 Continue asc. along S. slope.

79.64 The cor. of secs. 29, 30, 31 and 32.  
Land, mountainous.  
Soil, rocky loam; 3rd rate.  
Timber, fir, hemlock, pine and cedar.  
Undergrowth, vine maple, rhododendron, manzanita, laurel and hazel.

West, on a true line, bet. secs. 30 and 31.

Asc. 160 ft. along S. slope, through heavy timber and dense undergrowth.

13.00 Continue asc. over SE. slope.

15.30 Spur, slopes S.; desc. 50 ft. over SW. slope.

20.60 Dry ravine, course S.; thence along S. slope.

37.30 Brook, 1 lk. wide, course SE.; asc. 30 ft. over SE. slope.

40.00 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for  $\frac{1}{4}$  sec. cor., with brass cap marked

$$\begin{array}{r} \frac{1}{4} S30 \\ \frac{1}{4} S31 \\ 1927 \end{array}$$

from which

A fir, 18 ins. diam., bears S.48\*W., 36 lks. dist., marked  $\frac{1}{4}$  S 31 B T.

A hemlock, 10 ins. diam., bears N.10 $\frac{1}{2}$ \*W., 50 lks. dist., marked  $\frac{1}{4}$  S 30 B T.