

County Surveyor's Record, Douglas County, Oregon

Resurvey of the S. Rdy. of T. 25 S., R. 1 E .

CHAINS

A fir, 50 ins. in diam., bears N.7 $\frac{1}{2}$ *E., 56 lks.
dist., marked T. 25 S R 1 E S 36 B T

A fir, 40 ins. in diam., bears N.30*W., 49 lks.
dist., mkd. T 25 S R 1 E S 35 B T

Land, mountainous.

Soil, coarse gravelly loam, 2nd and 3rd rate.

Timber, fir, hemlock, pine and cedar.

Undergrowth, vinemaple, rhododendron and hazel.

West, on a true line on the S. bdy. of sec. 35
Asc. 230 ft. over E. slope, through heavy timber and
dense undergrowth.

- 5.20 Spur, slopes N.60*E., thence along N. slope.
- 11.75 Ascend 160 ft. over E. slope.
- 15.75 Spur, slopes N.; desc. 55 ft. over broken N. slope.
- 21.21 Point for the $\frac{1}{4}$ sec. cor. of sec. 36 only, later determined.
Set an iron post, 3 ft. long, 1 in. in diam., 27 ins. in
the ground, for the $\frac{1}{4}$ sec. cor. of sec. 36 only, with
brass cap mkd.

$\frac{1}{4}$ S36
1928

From which

A hemlock, 6 ins. in diam., bears S.35*E., 30 lks.
dist., mkd. $\frac{1}{4}$ S 36 B T

A hemlock, 12 ins. in diam., bears S.25*W., 26 lks.
dist., mkd. $\frac{1}{4}$ S 36 B T

- 33.50 Creek, 3 lks. wide, course N E.; ascend 130 ft. over NE.
slope.

- 39.90 Intersect the $\frac{1}{4}$ sec. cor. of sec. 35 only which is an
iron post, 1 in. in diam., protruding 9 ins. above
ground, with brass cap mkd.

$\frac{1}{4}$ S35
1927