

County Surveyor's Record, Douglas County, Oregon

Resurvey of the S. bdy. of T. 25 S., R. 1 E.

CHAINS

72.35 Spur, slopes NW.; desc. 20 ft. along N. slope.
 79.94 Intersect the cor. of secs. 33 and 34 only, which is an iron post, 2 ins. in diam., protruding 9 ins. above, ground, with brass cap mkd.

T25SR1E
S33 | S34

1927

From which the original bearing trees,

A cedar, 8 ins. in diam., bears N.74*E., 72 lks.

dist., mkd. T 25 S R 1 E S 34 B T

A cedar, 10 ins. in diam., bears N.55*W., 19 lks.

dist., mkd. T 25 S R 1 E S 33 B T

Land, mountainous.

Soil, coarse rocky loam; 3rd and 4th rate.

Timber, fir, pine, cedar and hemlock.

Undergrowth, vinemaple, rhododendron, hazel and huckleberry.

West, on a true line on the S. bdy. of sec. 33

Along N. slope, through heavy timber and dense undergrowth.

1.65 Brook, 1 lk. wide, course N.; asc. 200 ft. along broken N. slope.

12.00 Desc. 20 ft. over NW. slope.

15.00 Dry ravine, course NW.; asc. 105 ft. over NE. slope.

20.70 Spur, slopes N.; desc. 400 ft. over NW. slope.

21.62 Point for the $\frac{1}{4}$ sec. cor. of sec. 34 only, later determined.

Set an iron post, 3 ft. long, 1 in. in diam., 27 ins. in the ground, for the $\frac{1}{4}$ sec. cor. of sec. 34 only, with brass cap mkd.

$\frac{1}{4}$ S34

1928

From which

A cedar, 10 ins. in diam., bears S.25*E., 49 lks.

dist., mkd. $\frac{1}{4}$ S 34 B T