

County Surveyor's Record, Douglas County, Oregon

Resurvey of the S. bdy. of T. 25 S., R. 1 E.

CHAINS

Timber; fir, pine, cedar, and hemlock.

Undergrowth; vinemaple, rhododendron, and hazel.

Retracement of the S. Bdy. of sec. 36, T 25 S., R. 1 W.

From the cor. of Tps. 25 S., Rs. 1 W. and 1 E., as here-
inbefore described

West, on a random line on S. bdy. of sec. 36.

40.64 Fall 8 lks. S. of the old $\frac{1}{4}$ sec. cor.

57.89 The old closing Tp. cor. bears N. 16 lks. dist.

80.15 Fall 25 lks. S. of the cor. of secs. 35 and 36

The bearing and length of E. half mile is N.89°53'W.,
40.64 chs., and of the W. half mile is N.89°45'W.,
39.51 chs.

Resurvey of the S. bdy. of sec. 36, T. 25 S., R. 1 W.

From the cor. of Tp. 25 S., Rs. 1 W. and 1 E., as here-
in before described

Thence

N.89°53'W., on a true line on the S. bdy. of sec. 36.

Asc. 510 ft. over broken SE. slope, through timber and
brush.9.30 Rock Creek and Steamboat Bridge Trail, bears S.70°E.,
and N.70°W.

9.40 Spur, slopes S.70°E.

24.67 Point for the $\frac{1}{4}$ sec. cor. of sec. 31 only, later
determined.Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in
the ground, for the $\frac{1}{4}$ sec. cor. of sec. 31 only, with
brass cap mkd. $\frac{1}{4}$ S31

1928

From which