

County Surveyor's Record, Douglas County, Oregon

Survey of the E. bdy. of T. 25 $\frac{1}{2}$ S., R. 1 E.

CHAINS

R 1 E S 36 on the W. sides.

From which,

A fir, 30 ins. in diam., bears S.65*E., 91 lks.

dist., mkd. T 25 $\frac{1}{2}$ S R 2 E S 31 C C B T

A fir, 32 ins. in diam., bears S.25*W., 46 lks.

dist., mkd. T 25 $\frac{1}{2}$ S R 1 E S 36 C C B T

Land, mountainous.

Soil, rocky loam; 3rd rate.

Timber, fir, hemlock and madrone

Undergrowth, vinemape and rhododendron.

Subdivisions, T. 25 $\frac{1}{2}$ S., R. 1 E.

From the cor. of secs. 1, 2, 35 and 36 on the S. bdy. of the township, as described in the notes of T. 26 S., R. 1 E.

Thence,

N.0*01'W., bet. secs. 35 and 36.

Descend 430 ft. over broken N. slope, through timber and brush.

33.10 Creek, 2 lks. wide, course NE.

34.41 Intersect the N. bdy. of the Tp., 18.64 chs. E. of the cor: of secs. 34 and 35 only, hereinbefore described.

At point of intersection;

Set an iron post, 3 ft. long, 2 ins. in diam., 27 ins. in the ground; for the closing cor. of secs. 35 & 36, with brass cap mkd.

T25SR1E
 S35

 S35|S36
 T25 $\frac{1}{2}$ SR1E
 C C
 1928

From which,