

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of S. Bdy. T. 24 S., R. 3 E.

CHAINS

Thence

N.89°58'W., on true line bet. secs. 1 and 36

Along steep S. slope.

- 0.57 Mid point on N. bdy of sec. 1, as hereinafter determined; set an iron post, 3 ft. long, 1 in diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor. of sec. 1 only, with brass cap mkd.

$$\frac{1}{4} \text{ S } 1$$
 1931

from which

A fir, 42 ins. diam., bears S. 80°E., 49 lks.

dist., mkd. $\frac{1}{4}$ S 1 B T

A fir, 18 ins. diam., bears S.62°W., 74 lks.

dist., mkd. $\frac{1}{4}$ S 1 B T

Desc. 642 ft. over broken rocky SW. slope, over bluffs

- 17.50 Rocky spur, slopes SW.,
- 20.80 Creek, 1 lk. wide, course S., asc. 57 ft. over SE. slope
- 24.80 Rocky spur, slopes S., desc. 233 ft. over SW. slope.
- 34.10 Draw, drains S., along broken S. slope.
- 38.86 The cor. of secs. 35 and 36 only, which is an iron post, 2 ins. diam., firmly set in a mound of stone 4 ft. base, 2 ft. high, mkd. and witnessed as described in the official record.

Land; mountainous.

Soil; rocky, 4th rate.

Timber; fir, hemlock, pine, and cedar.

Undergrowth; rhododendron, vinemaple, and arrow wood.

S.89°28'W., on true line bet. secs. 1 and 35

Asc. 23 ft. over broken SE. slope. through scattered timber and light undergrowth

- 1.82 Point for closing cor. of secs. 1 and 2, as hereinafter determined