

Dependent Resurvey of S. Bdy. of T. 24 S., R. 3 E.

CHAINS

2 ins. diam., 10 ins. above ground, firmly set, mkd.  
and witnessed as described in the official record.

Land; mountainous.

Soil; mountain loam, 3 rd rate.

Timber; fir, hemlock, cedar, pine, and yew.

Undergrowth; vinemaple, rhododendron, hazel, and alder.

S.89°58'W., on true line bet. secs. 5 and 31  
Asc. 18 ft. over E. slope, through heavy timber  
and medium undergrowth.

1.55 Point for closing cor., of secs. 5 and 6, as  
hereinafter determined

Thence, bet. secs. 6 and 31; continue line and  
measurement.

Asc. 674 ft. over SE. slope.

39.72 The  $\frac{1}{4}$  sec. cor. of sec. 31 only, which is an iron  
post, 1 in. diam., firmly set in mound of stone,  
 $3\frac{1}{2}$  ft. base, 2 ft. high, mkd. and witnessed as  
described in the official record.

Thence,

N.89°33'W. on true line bet. secs. 6 and 31

Spur, slopes N., desc. 14 ft. over SW. slope.

1.83 At 40.00 chs. westing from the closing cor. of secs.  
5 and 6, as hereinafter determined; a fir, 22 ins.  
diam., for the  $\frac{1}{4}$  sec. cor. of sec. 6 only, mkd.

$\frac{1}{4}$  S 6 on S. side.

from which

A fir, 22 ins. diam., bears S.27°E., 64 lks.  
dist., mkd.  $\frac{1}{4}$  S 6 B T

A fir, 36 ins. diam., bears S.77°W., 98 lks.  
dist., mkd.  $\frac{1}{4}$  S 6 B T

Desc. 642 ft. over SW. slope.