


County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 25 S., R. 3 E.

CHAINS

for the $\frac{1}{4}$ sec. cor., with brass cap mkd.



from which

A yew. 6 ins. diam., bears east, 74 lks.

dist., mkd. $\frac{1}{4}$ S 12 B T

A fir, 38 ins. diam., bears west, 103 lks.

dist., mkd. $\frac{1}{4}$ S 11 B T

Desc. 189 ft. over NW. slope.

52.50 Creek, 4 lks. wide, course W., asc. 113 ft. over SW. slope.

58.70 Spur, slopes SW., desc. 231 ft. over broken NW. slope.


72.30 Creek, 2 lks. wide, course W., asc. 186 ft. over broken SW. slope, along face of bluffs, 80 ft. high

80.00 Point for cor. of secs. 1, 2, 11, and 12, falls on face of bluff, impracticable to set cor.

Thence

N.89°54'E., 80 lks. dist.

Set an iron post, 3 ft. long, 2 ins. diam., 10 ins. in the ground to bedrock, and in a mound of stone to top for witness cor. of secs 1, 2, 11, and 12, with brass cap mkd.



from which

A fir, 16 ins. diam., bears N.58°E., 43 lks.

dist., mkd. W C T 25 S R 3 E S 1 B T

A fir, 24 ins. diam., bears S.48°E., 78 lks.

dist., mkd. W C T 25 S R 3 E S 12 B T

A fir, 20 ins. diam., bears S.32°W., 35 lks.

dist., mkd. W C T 25 S R 3 E S 12 B T