


County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 25 S., R. 3 E.

CHAINS

Slope.

- 59.60 Creek, 1 lk. wide, course SE.,
- 62.90 Spur, slopes E., desc. 129 ft. over broken NE. slope.
- 66.70 Creek, 1 lk. wide, course SE.,
- 69.20 Creek, 1 lk. wide, course E., asc. 134 ft. over broken SE. slope.
- 73.40 Small stream, course SE.,
- 76.00 Spur, slopes E., desc. 63 ft. over NE. slope.
- 78.80 Enter meadow, bears E. and W.,
- 80.00 Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, for the cor. of lots 5 and 12, sec. 3, and lots 8 and 9, sec. 4, with brass cap mkd.




from which

A fir, 42 ins. diam., bears N.35°E., 141 lks. dist., mkd. S 3 L 5 B T

A fir, 40 ins. diam., bears N.59°W., 177 lks. dist., mkd. S 4 L 8 B T

Desc. 62 ft. over NE. slope.

- 85.90 Draw, course S.70°E., asc. 170 ft. over SE. slope, through heavy timber and dense undergrowth.
- 103.30 Calapooya Mountains, divide bet. the North Umpqua and the Willamette rivers, bears NE. and SW., along gradual W. slope.
- 104.12 Intersect the S. bdy. of T. 24 S., R. 3 E.
Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, for closing cor. of secs. 3 and 4, with brass cap mkd.



from which