

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 25 S., R. 3 E.

CHAINS

and 33, with brass cap mkd.

$$\frac{1}{4} \frac{WC}{S28}$$

$$S33$$

$$1931$$

from which

A fir, 20 ins. diam., bears S.19°E., 18 lks.

dist., mkd. WC $\frac{1}{4}$ S 33 B T

A fir, 26 ins. diam., bears N.79°W., 95 lks.

dist., mkd. WC $\frac{1}{4}$ S 28 B T

Along N. Slope.

48.50 Spur, slopes N.60°W., desc. 475 ft. over broken SW. slope

61.90 Branch of Boulder Creek, 8 lks. wide, course S., asc.

303 ft. over broken SE. slope, to cor.

72.60 Draw, course S.15°E.,

79.76 Cor. of secs. 28, 29, 32, and 33

Land; mountainous.

Soil; rocky, 4th rate.

Timber; fir, cedar, pine, hemlock, madrona, yew, and

Oregon maple.

Undergrowth; vinemaple, alder, mountain laurel,

rhododendron, hazel, huckleberry, manzanita,

chinquapin, and buckbrush.

N.0°03'W., bet. secs. 28 and 29

Asc. 239 ft. over SE. slope, through medium timber and
dense undergrowth.

14.00 Spur, slopes E., desc. 65 ft. along broken NE. slope.

32.00 Creek, 2 lks. wide, course E.,

34.00 Creek, 1 lk. wide, course E.,

37.90 Creek, 1 lk. wide, course S.75°E., asc. 41 ft. over SE.
slope.40.00 Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in
the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.