


County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 25 S., R 3 E.

CHAINS



from which

A fir, 6 ins. diam., bears N.74°E., 21 lks.

dist., mkd.  $\frac{1}{4}$  S 28 B T


A pine, 32 ins. diam., bears N.49°W., 88 lks.

dist., mkd.  $\frac{1}{4}$  S 29 B T

Along broken E. slope, through heavy timber and dense undergrowth.

49.30 Creek, 2 lks. wide, course SE., asc. 535 ft. over SE. slope.

80.00 Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for the cor. of secs. 20, 21, 28, and 29, with brass cap mkd.



from which

A fir, 12 ins. diam., bears N.23°E., 32 lks.

dist., mkd. T 25 S R 3 E S 21 B T

A fir, 14 ins. diam., bears S.48°E., 78 lks.

dist., mkd. T 25 S R 3 E S 28 B T

A hemlock, 16 ins. diam., bears S.30°W., 94 lks.

dist., mkd. T 25 S R 3 E S 29 B T

A fir, 56 ins. diam., bears N.28°W., 76 lks.

dist., mkd. T 25 S R 3 E S 20 B T

Land; mountainous.

Soil; rocky, 4th rate.

Timber; fir, hemlock, pine, cedar, madrona, and yew.

Undergrowth; vinemaple, rhododendron, buckbrush, manzanita, and chinquapin.

S.89°50'E., on a random line bet. secs. 21 and 28