

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 25 S. R. 3 E.

CHAINS

- 40.00 Set temp. $\frac{1}{4}$ sec. cor.
- 79.56 Intersect N. and S. line, 30 lks. S. of the cor. of
secs. 21 and 22, 27, and 28
- Thence
- S. $89^{\circ}57'W.$, on true line bet. secs. 21 and 28
- Asc. 341 ft. over E., changing to SE. slope, through
heavy timber and medium undergrowth.
- 9.30 Spur, slopes S. $20^{\circ}E.$, along broken rocky S. slope.
- 22.40 Asc. 100 ft. over SE. slope.
- 32.50 Spur, slopes SW. desc. 199 ft. over W. slope.
- 39.78 Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in
the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.
- | | | |
|---------------|------------|--|
| $\frac{1}{4}$ | <u>S21</u> | |
| | S28 | |
| | 1931 | |
- from which
- A fir, 28 ins. diam., bears N. $10^{\circ}E.$, 30 lks.
dist., mkd. $\frac{1}{4}$ S 21 B T
- A fir, 20 ins. diam., bears S. $24^{\circ}E.$, 60 lks.
dist., mkd. $\frac{1}{4}$ S 28 B T
- Desc. 265 ft. over W. slope.
- 48.90 Small stream, course S. $35^{\circ}W.$, desc. 118 ft. over
SW. slope.
- 53.50 Branch of Boulder Creek, 7 lks. wide, course S.,
asc. 335 ft. over broken SE. slope, to cor.
- 66.10 Spur, slopes S.,
- 67.40 Creek, 3 lks. wide, course S. $15^{\circ}E.$,
- 68.80 Spur, slopes SE.,
- 79.56 The cor. of secs. 20, 21, 28, and 29
- Land; mountainous.
- Soil; rocky, 4th rate.
- Timber; fir, pine, hemlock, cedar, yew, and madrona.
- Undergrowth; vinemaple, manzanita, rhododendron
mountain laurel, and buckbrush.