

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 25 S., R. 3 E.

CHAINS

A fir, 58 ins. diam., bears S.41°W., 68 lks.
dist., mkd. $\frac{1}{4}$ S 21 B T

A fir, 10 ins. diam., bears N.54°W., 48 lks.
dist., mkd. $\frac{1}{4}$ S 16 B T

Along broken S. slope.

43.00 Desc. 63 ft. along SW. slope.

48.80 Spur, slopes SW., desc. 71 ft. over NW. slope.

50.20 Creek, 3 lks. wide, course S.15°W., asc. 134 ft. over
SE. slope.

55.20 Spur, slopes S., desc. 96 ft. over SW. slope.

58.30 Creek, 2 lks. wide, course S.20°E., asc. 138 ft.
over E. slope.

63.40 Spur, slopes SE., along S. slope.

76.40 Asc. 34 ft. over SE. slope.

79.64 The cor. of secs. 16, 17, 20, and 21

Land; mountainous.

Soil; rocky, 4th rate.

Timber; fir, hemlock, cedar, pine, and yew.

Undergrowth; vinemaple, alder, huckleberry, mountain
laurel, manzanita, chinquapin, buckbrush, and dog
wood.

N.0°03'W., bet. secs. 16 and 17

Asc. 469 ft. over SE. slope, through heavy timber
and medium undergrowth.

13.20 Spur, slopes E., along broken E. slope.

22.10 Creek, 3 lks. wide, course S.75°E., asc. 425 ft. over
SW. slope, through fir thicket.

40.00 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in
the ground, for the $\frac{1}{4}$ sec. cor., with brass cap mkd.

$\frac{1}{4}$
 |
 S17 | S16
 |
 1931

from which